



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
ASHFURLONG ROAD	O/S 33, (bottomside, closer to driveway 1 of 2)	Dangerous	Stem decayed, cavity at crown break	Malus sp	Plant in verge o/s 33, (same position as felled tree)	Crataegus laevigata 'Paul's Sc
ASHFURLONG ROAD	O/S 6	Damaging	Kerb missing and f/w and edgings disrupted	Prunus Kanzan	Plant in new 800 pit o/s 6, (same position as felled tree)	Crataegus laevigata 'Paul's Sc
ASHFURLONG ROAD	O/S 8	Damaging	Kerbs displaced and f/w disrupted	Prunus Kanzan	Plant in existing pit o/s 8, (same position as felled tree)	Crataegus laevigata 'Paul's Sc
ASHFURLONG ROAD	o/s 18	Damaging	Kerbs displaced	Prunus Kanzan	Plant in new 800mm pit o/s 18, (same position as felled tree)	Crataegus laevigata 'Paul's Sc
ASHFURLONG ROAD	O/S 20 (topside, upper most 1 of 2 o/s 20)	Damaging	Kerbs displaced and f/w mounded	Prunus Kanzan	Plant in existing pit o/s 20, (same position as felled tree)	Crataegus laevigata 'Paul's Sc
ASHFURLONG ROAD	O/S 16	Dangerous	significant basal decay	Prunus Kanzan	Plant in existing pit o/s 16	Malus 'Rudolph'
ASHFURLONG ROAD	O/S 35	Dangerous	significant stem cavity, structural integrity in doubt	Malus sp	Plant in verge o/s 35 (same as old tree)	Malus 'Rudolph'
ASHFURLONG ROAD	O/S 4	Dangerous	cavity at crown break and footway disturbance, poor specimen	Prunus Kanzan	Plant in existing pit o/s 4 (same as felled tree)	Malus 'Rudolph'
ASHFURLONG ROAD	O/S 15	Dangerous	decayed roots where severed historically at buttress, lions tailed and significant crown deadwood	Fraxinus Excelsior	Plant in verge o/s 15 (same as felled tree)	Quercus robur